



REV	DATE	REMARKS	APPRO.
1	5-30-95	pipe structure Expansion/pipe Cracking	9-18-95
2	6-13-95	Ditch D-10D Route Modified (35)	9-18-95
3	12-02-95	Boundary Mod./Cul. Recovery Bin. Removed (35)	12-18-95
4	6-08-95	Dist. Boundary Mod. for BITA Area "A" (35)	1-08-96
5	2-23-96	Plans updated for Tank Sump/Bathhouse As-built (96)	9-04-96
6	7-22-96	D-8D Water Bar Concrete Crossing Added (96C)	9-04-96
7	3-18-98	Lower Culvert C-2D Removed	4-15-98
8	6-23-01	Wild Horse Ridge Disturbance Area Added (SR98-1)	7-28-01
9	6-23-01	Changed from plate 8-1 to 2-1A	7-28-01
10	1-16-07	Loadout Expansion	8-07-07

LEGEND	
DISTURBED AREA	D
SOIL BOUNDARY	-----
DATINO-SHEEPSCAN-MINNETTI	DZE
SECTION LINE	— — — — —
CONTOUR LINE	~7350~
PADO-DATINO-ROCK	PDR
PERMIT BOUNDARY	-----
SURVEY BOUNDARY	— — — — —
TRAVESSILLA	TR

